§ 63.8786

§63.8786 When do I have to comply with this subpart?

- (a) If you have a new or reconstructed affected source, you must comply with this subpart according to paragraphs (a)(1) and (2) of this section.
- (1) If you start up your new or reconstructed affected source before April 14, 2003, then you must comply with the emission standards for new or reconstructed sources in this subpart no later than April 14, 2003.
- (2) If you start up your new or reconstructed affected source on or after April 14, 2003, then you must comply with the emission standards for new or reconstructed sources in this subpart upon startup of your affected source.
- (b) If you have an existing loop slitter affected source, you must comply with the emission standards for existing sources no later than 1 year after April 14, 2003.
- (c) If you have an area source that increases its emissions or its potential to emit such that it becomes a major source of HAP and an affected source subject to this subpart, the provisions in paragraphs (c)(1) and (2) of this section apply.
- (1) A new affected source as specified at §63.8784(c) or a reconstructed affected source as specified at §63.8784(d) must be in compliance with this subpart upon startup.
- (2) An existing affected source as specified at §63.8784(e) must be in compliance with this subpart no later than 1 year after the date on which the area source became a major source.
- (d) You must meet the notification requirements in §63.8816 according to the schedule in §63.8816 and in subpart A of this part. Some of the notifications must be submitted before you are required to comply with the emission standards in this subpart.
- (e) If you have a loop slitter affected source, you must have data on hand beginning on the compliance date specified in paragraph (b) of this section as necessary to demonstrate that your adhesives are not HAP-based. The types of data necessary are described in §§ 63.8802 and 63.8810.

EMISSION LIMITATIONS

§ 63.8790 What emission limitations must I meet?

- (a) You must meet each emission limit in Table 1 to this subpart that applies to you.
- (b) You must meet each operating limit in Table 2 to this subpart that applies to you.

GENERAL COMPLIANCE REQUIREMENTS

§ 63.8794 What are my general requirements for complying with this subpart?

- (a) For each loop slitter adhesive use affected source, you must be in compliance with the requirements in this subpart at all times.
- (b) For each new or reconstructed flame lamination affected source, you must be in compliance with the requirements in this subpart at all times, except during periods of startup, shutdown, and malfunction.
- (c) You must always operate and maintain your affected source, including air pollution control and monitoring equipment, according to the provisions in §63.6(e)(1)(i).
- (d) During the period between the compliance date specified for your new or reconstructed flame lamination affected source in §63.8786, and the date upon which continuous compliance monitoring systems have been installed and verified and any applicable operating limits have been set, you must maintain a log detailing the operation and maintenance of the process and emissions control equipment.
- (e) For each new or reconstructed flame lamination affected source, you must develop a written startup, shutdown, and malfunction plan according to the provisions in §63.6(e)(3).
- (f) For each monitoring system required in this section for new or reconstructed flame lamination sources, you must develop and submit for approval a site-specific monitoring plan that addresses the requirements in paragraphs (f)(1) through (3) of this section.
- (1) Installation of the continuous monitoring system (CMS) sampling probe or other interface at a measurement location relative to each affected process unit such that the measurement is representative of control of the

Environmental Protection Agency

exhaust emissions (e.g., on or downstream of the last control device);

- (2) Performance and equipment specifications for the sample interface, the pollutant concentration or parametric signal analyzer, and the data collection and reduction system; and
- (3) Performance evaluation procedures and acceptance criteria (e.g., calibrations).
- (g) In your site-specific monitoring plan, you must also address the ongoing procedures specified in paragraphs (g)(1) through (3) of this section.
- (1) Ongoing operation and maintenance procedures in accordance with the general requirements of §§ 63.8(c)(1), (3), (4)(ii), (7), and (8), and 63.8804;
- (2) Ongoing data quality assurance procedures in accordance with the general requirements of §63.8(d); and
- (3) Ongoing recordkeeping and reporting procedures in accordance with the general requirements of §63.10(c), (e)(1), and (e)(2)(i).

[68 FR 18070, Apr. 14, 2003, as amended at 71 20470, Apr. 20, 2006]

TESTING AND INITIAL COMPLIANCE REQUIREMENTS

§ 63.8798 By what date must I conduct performance tests or other initial compliance demonstrations?

- (a) For each loop slitter affected source, you must conduct the initial compliance demonstration by the compliance date that is specified for your source in §63.8786.
- (b) For each new or reconstructed flame lamination affected source, you must conduct performance tests within 180 calendar days after the compliance date that is specified for your source in §63.8786 and according to the provisions in §63.7(a)(2).

§63.8800 What performance tests and other procedures must I use to demonstrate compliance with the emission limit for flame lamination?

- (a) You must conduct each performance test in Table 3 to this subpart that applies to you.
- (b) Each performance test must be conducted according to the requirements in §63.7(e)(1) and under the specific conditions in Table 3 to this subpart.

- (c) You may not conduct performance tests during periods of startup, shutdown, or malfunction, as specified in §63.7(e)(1).
- (d) You must conduct at least three separate test runs for each performance test required in this section, as specified in §63.7(e)(3). Each test run must last at least 1 hour.
- (e) You must determine the percent reduction of HAP emissions during the performance test according to paragraphs (e)(1) through (3) of this section.
- (1) If you use chlorinated fire retardant foams, determine the percent reduction of HCl to represent HAP emissions from the source. If you do not use chlorinated fire retardant foams, determine the percent reduction of HCN to represent HAP emissions from the source.
- (2) Calculate the concentration of HAP at the control device inlet and at the control device outlet using the procedures in the specified test method.
- (3) Compare the calculated HAP concentration at the control device inlet to the calculated HAP concentration at the control device outlet to determine the percent reduction over the period of the performance test, using Equation 1 of this section:

$$R = \frac{\sum_{i=1}^{n} E_{inlet, i} - \sum_{i=1}^{n} E_{outlet, i}}{\sum_{i=1}^{n} E_{inlet, i}} (100) \text{ [Eq. 1]}$$

Where:

R=Efficiency of control device, percent.

$$\begin{split} &E_{inlet,i}\text{=}HAP \ concentration \ of \ control \ device} \\ &inlet \ stream \ for \ test \ run \ i, \ mg/dscm. \end{split}$$

$$\begin{split} E_{outlet,i} \!\!=\!\! HAP \ concentration \ of \ control \ device \\ outlet \ stream \ for \ test \ run \ i, \ mg/dscm. \end{split}$$

n=Number of runs conducted for the performance test.

- (f) You must also meet the requirements in paragraphs (f)(1) and (2) of this section.
- (1) Conduct the performance tests using foams that are representative of foams typically used at your flame lamination affected source. If you use foams containing chlorinated fire retardants, you must conduct the performance tests using these foams.
- (2) Establish all applicable operating limits that correspond to the control